

Alignment Assessment Overview

- Timmins: Schumacher Terminal Option
 - Review of the route on Google Earth Street view shows areas where track is overgrown with vegetation, grade crossings that have been built over with no visible track and areas where some utilities look to be within the horizontal and vertical clearance of the vehicle structure gauge. This would need to be confirmed by a detailed survey.

